# Technical product information

Topic	8 speed transmission - front differential noi					
Market area	Worldwide Bentley (1WBE)					
Brand	Bentley					
Transaction No.	2032542/1					
Level	EH					
Status	Approval					
Release date						

#### New customer code

Object of complaint	Complaint type	Position
Drivetrain -> Operation, shift and power flow control	Noise, vibration	

#### New workshop code

Object of complaint	Complaint type	Position
Drivetrain -> Transfer case, differential, torque split -> Bevel pinion shaft bearing	component / consumables ->	front
Drivetrain -> Transfer case, differential, torque split -> Bevel pinion shaft bearing	component / consumables -> cracked/broken	front
Drivetrain -> Transfer case, differential, torque split -> Bevel pinion shaft bearing	component / consumables -> damaged	front
Drivetrain -> Transfer case, differential, torque split -> Bevel pinion shaft bearing	Noise, vibration -> sing	front

## Vehicle data

## Continental V8T and New GT Speed

#### Sales types

Туре	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
39314B	2013	E		*	*	*
3932*	2012	E		*	*	*

Туре	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3932*	2013	E		*	*	*
3942*	2012	E		*	*	*
3942*	2013	E		*	*	*

#### Chassis numbers

Manufacturer	Filler	Туре	Filler	MY	Factory	From	То	Prod from	Prod to
SCB	???	**	*	С	С				


## **Documents**

Document name master.xml

## Customer statement / workshop findings

Noise from Transmission/Gearbox/Differential or Axle when 'coasting'/ lifting off the accelerator,

# Technical background



A small number of 8 speed transmissions have developed a front differential noise in service. Subsequent investigations of these replaced units identified a reduction in the torque of the nut (A) retaining the front differential bevel gear bearing. Front differentials where the clamping load on this bearing has relaxed will become noisy and have a greatly reduced service life

## Production change

The surface finish and method of locking the bevel gear bearing retaining nut has been changed

### Measure

As the front axle final drive unit is not serviceable and is integral with the main transmission assembly a qualified complaint of this nature can only be rectified by fitting a new transmission assembly.

# Warranty accounting instructions

Contact your TSC before replacing the transmission for this concern

In each instance the DISS BAID entry will be required to support your warranty claim