
Technical Service Bulletin



Bulletin	GROUP	
	ENGINE MECHANICAL	
	NO.	
	08-20-004	
SUBJECT	DATE	
	FEBRUARY 4, 2008	
REPLACEMENT OF AIR INTAKE HOSE CLAMPS (F/FIX)	MODEL	
	TUCSON	

This bulletin replaces 05-20-010-1 to include revisions to the WARRANTY INFORMATION.

Some Tucson (JM) vehicles with 2.7L engines may experience rough idle and illumination of the check engine light. This may be caused by loose air intake hose clamps around the Mass Air Flow Sensor.



A new type clamp is available that provides a more secure attachment.

This bulletin outlines the service procedure to remove and replace the intake hose clamps with corresponding part numbers.

AFFECTED VEHICLES:

All Tucson (JM) vehicles with 2.7L engines produced through March 25, 2005

DISTRIBUTION:	Dealer Principal	Service Manager	Parts Manager	Sales Manager	Service Technicians
		-	-	-	





GROUP

ENGINE MECHANICAL

NO.


08-20-004

PARTS INFORMATION:

PART	PART N	REMARKS	
NAME	OLD	NEW	KEWAKKS
Hose Clamp	Ot		2 required
	14711-90006B	28192-2E500	
	Wire type clamp	Band type clamp	

REPAIR PROCEDURE:

- Ensure that the vehicle is within the affected vehicle production date range, and has the wire type clamp around the Mass Air Flow Sensor.
- 2. Turn the ignition to the off position.
- 3. Disconnect the Mass Air Flow Sensor.
- 4. Loosen the two wire type hose clamps and remove the Mass Air Flow Sensor.



Technical Service Bulletin



GROUP

ENGINE MECHANICAL

NO.

08-20-004

5. Remove the old wire type hose clamps.



Install the new band type hose clamps on the two intake hoses.



7. Reinstall the Mass Air Flow Sensor and tighten the new hose clamps.

Tightening Torque: 0.4-0.5 (2.9-3.6) kgf.m (lb.ft)

8. Plug in the Mass Air Flow Sensor.



WARRANTY INFORMATION:

OFP: 14711-90006B (QTY 0)

28192-2E500 (QTY 2)

Description: Replacement of air intake hose clamps

OP Code: 28164F00

T1: N69 (Warning lights ON)
T2: C90 (Loose fitting)

LTS: 0.3 Hours

3