# Service Bulletin Mazda North American Operations

Irvine, CA 92618-2922



© 2008 Mazda Motor of America, Inc.

Subject: MIL ON - P2070 SET	Bulletin No:	01-019/08
	Last Issued:	4/18/2008

# **BULLETIN NOTE**

This bulletin supersedes the previous bulletin 01-019/08, issued 3/21/2008. The WARRANTY INFORMATION has been revised.

# APPLICABLE MODEL(S)/VINS

2004-2007 RX-8 vehicles with VINs lower than JM1 FE\*\*\*\* \*\* 213322 (built before April 18, 2007)

# **DESCRIPTION**

Some vehicles may experience a MIL with DTC P2070 (SSV Stuck Open). This may be caused by carbon build up near the SSV bushing, which may cause driveability concerns (hesitation and / or lack of power) and / or DTC P2070. A cleaning procedure and a revised SSV with stronger actuator force is now available.

Customers having this concern should have their vehicle repaired using the following repair procedure.


#### REPAIR PROCEDURE

- 1. Verify the following:
  - P2070 is set.
  - SSV sticks without failure of SSV solenoid valve switch.
- 2. Record freeze frame data.
- 3. Record customer radio station presets.
- 4. Disconnect negative battery cable.
- 5. Raise and support vehicle.
- 6. Drain engine coolant into a clean container for reuse after repair. Refer to Workshop Manual section 01-12 ENGINE COOLANT REPLACEMENT.
- 7. Remove right front wheel.
- 8. Remove rubber splash shield from inner fender to access right side of engine.


 Bulletin No:
 01-019/08
 Last Issued:
 4/18/2008

 © 2008 Mazda Motor of America, Inc.
 Last Issued:
 4/18/2008

9. Remove 2 nuts (1) attaching air pipe (2) to exhaust manifold (3).



10. Disconnect port air bleed vacuum hose (4) from intake manifold.




- 11. Lower vehicle.
- 12. Remove battery cover, battery and battery tray to make work space. Refer to Workshop Manual section 01-17 BATTERY REMOVAL / INSTALLATION.


 Bulletin No:
 01-019/08
 Last Issued:
 4/18/2008

 © 2008 Mazda Motor of America, Inc.
 4/18/2008

13. Remove air control valve bracket bolt (5).





- 14. Disconnect main harness from air control valve bracket.
- 15. Disconnect upper hose (6) and vacuum line (7) from air control valve.
- 16. Position air control valve and air pipe out of the way by moving toward washer fluid reservoir.
- 17. Loose 3 water pump pulley bolts (8) but do not remove.



<b>Bulletin No:</b> 01-019/08	Last Issued: 4/18/2008
© 2008 Mazda Motor of America, Inc.	


- 18. Loosen alternator belt tension bolt and remove attaching bolt and nut (9) from alternator and bracket.
- 19. Remove alternator belt.
- 20. Remove water pump pulley.
- 21. Remove 3 nuts (10) and alternator bracket (11).
- 22. Raise and support vehicle.
- 23. Remove 2 bolts (12) attaching port air bleed vacuum pipe.





<b>Bulletin No:</b> 01-019/08	Last Issued: 4/18/2008
© 2008 Mazda Motor of America, Inc.	

- 24. Remove 2 lower nuts (13) on thermostat housing.
- 25. Lower vehicle.
- 26. Remove 1 upper nut on thermostat housing.
- 27. Carefully position oil metering lines and bracket away from upper thermostat housing stud as to be able to remove thermostat housing from mounting studs.
- 28. Remove thermostat housing from mounting studs and position toward front of vehicle to allow access to SSV
- 29. Position main harness to the side to allow access to SSV.
- 30. Disconnect SSV switch connector (14).



31. Remove 2 bolts (15) attaching SSV.

#### NOTE:

- The upper SSV bolt will not be reused for assembly. A longer bolt is provided.
- 32. Pull out SSV using a slow twisting motion.

#### NOTE:


• Ensure sufficient working space is available to access the SSV port in the next steps.

<b>Bulletin No:</b> 01-019/08	Last Issued: 4/18/2008
© 2008 Mazda Motor of America, Inc.	

33. Wrap a shop towel around the handle of a screwdriver (or equivalent) and use a zip-tie to secure the towel at the handle end.

# NOTE:

• Ensure the screwdriver handle (or equivalent) is as close to 1/2" (12mm) as possible.



34. Place a rag in SSV port of intake manifold to catch carbon deposits (debris).

#### NOTE:


- A shop rag may need to be cut in half to fit properly to allow access to the bushing at the rear of the port.
- 35. Hold engine cleaner up-right and spray inside the SSV port, focusing on the bushing (16) located at the rear of the port.

# **WARNING:**

- PLEASE USE CAUTION WHEN USING ENGINE CLEANER.
- WEAR EYE PROTECTION AND GLOVES WHEN HANDLING.
- ENGINE CLEANER IS FLAMMABLE.

#### NOTE:

• 1 can of engine cleaner is sufficient for 2 engine cleanings.




36. Wait five (5) minutes after spraying.

<b>Bulletin No:</b> 01-019/08	Last Issued: 4/18/2008
© 2008 Mazda Motor of America, Inc.	

37. Using screwdriver with rag wrapped around the end, clean inner surface of SSV port.

# **CAUTION:**


• Use care to restrict the amount of carbon debris that falls into the intake manifold ports.



- 38. Install modified SSV and gasket. Install modified longer bolt (9979-60-640) in the upper mounting hole.
- 39. Assemble in the reverse order of removal.

#### **IMPORTANT:**

- Follow the tightening procedure below when installing air pipe and air control valve.
- Hand-tighten nuts (1, 2) first then hand-tighten bolt (3). Tighten nuts (1, 2 then 3) to 69.1-95.5 in-lbf. (7.8-10.8Nm).



- 40. Connect negative battery cable.
- 41. Fill engine coolant system using coolant removed from engine and purge air out of the cooling system. Refer to Workshop Manual section 01-12 ENGINE COOLANT REPLACEMENT.

Bulletin No: 01-019/08	Last Issued: 4/18/2008
© 2008 Mazda Motor of America, Inc.	

- 42. Check SSV function. Refer to workshop manual section 01-03 SECONDARY SHUTTER VALVE (SSV) OPERATION INSPECTION.
- 43. Set recorded customer radio station presets.
- 44. Set clock.
- 45. In equipped with DSC, perform steering angle sensor initialization procedure. Refer to Workshop Manual section 04-15 STEERING ANGLE SENSOR INITIALIZATION PROCEDURE.
- 46. Verify repair.

# **PART(S) INFORMATION**

Part Number	Description	Qty.	Notes
N3H5-20-160F	Vavle, Shutter- Manifold (SSV)	1	
N3H4-20-155A	Gasket, SSV	1	
9979-60-640	Bolt	1	Longer upper SSV bolt
N3H1-13-996	Gasket, ACV	1	
0000-77-A86	Engine Cleaner	1	Quantity 1 = 1 can of engine cleaner when ordered through eMDCS.
			1 can of engine cleaner is sufficient for 2 engine cleanings.

Bulletin No: 01-019/08	Last Issued: 4/18/2008
© 2008 Mazda Motor of America, Inc.	

# **WARRANTY INFORMATION**

# NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	А
Symptom Code	6X
Damage Code	93
Part Number Main Cause	N3H5-20-160F
Quantity	1
Related Part Number - Reimbursement Engine cleaner	5555-08-008A Allowance applies to 1/2 can of engine cleaner per repair
Related Part Number Quantity	1
Operation Number / Labor Hours:	XXC31XRX / 1.6 Hrs