	TCD	Model	SORENTO(XM) (2011)
KIA	TSB Local	Group	Fuel System (14)
	LUCAI	TSB No.	KCE13-14-P160- SLXMVQ
Subject		TSB Type	Service Action
R-Engine Fuel Feed Hose Replacement		Published	

Description

This bulletin is issued to provide information about the fuel feed hose replacement. The fuel feed hose on Sorento (XM) vehicles equipped with R-engine has been newly improved to prevent the early deterioration of fatigability-resistant and/or oil-proof.

Check campaign look up site, if VIN is listed replace the fuel feed hose with a new one by following the Service Procedure below.

Applicable Vehicles

Model	Applicable vehicle production date range	Applicable VIN range	Remark
Sorento (XM)	Aug. 29 , 2011 ~	KNAKT814BC5240407 ~	Equipped with R-
	Dec. 29, 2011	KNAKU815CC5254035	Engine

■ Area: All except North America

Parts Information



Operation Code And Time

Model	OP CODE	OPERATION	OP TIME
XM	130137R0	R-Engine Fuel Feed Hose Replacement	0.2 M/H

Service Procedure

NOTE

Before conducting this procedure, verify that the vehicle is included in the attached VIN list.

If not, no further procedure is required.

Fuel Feed Hose Replacement

1. Remove the engine cover and remove the mounting bolt (A) of the fuel feed hose.



Tightening Torque : $4.9 \sim 5.9 \text{ Nm} (0.5 \sim 0.6 \text{ kgf.m}, 3.6 \sim 4.3 \text{ lb-ft}$

NOTE

Re-use the bracket and bolt (A).

2. Disconnect the fuel feed hose adapter (B) by pressing the locking hooks of the quick-connector.



NOTE

When disconnecting the fuel feed hose adapter (B), place a shop towel under the adapter.

3. Unclip the fixing clip (C) and disconnect the fuel feed hose.



NOTE

When disconnecting the fuel feed hose, place a shop towel under the hose.

4. Replace the affected fuel feed hose with a new one and install all the removed parts in the reverse order of removal.



CAUTION

After completing the above Service Procedure, check if any fuel from the fuel line connections leaks or not.