

Inner Rear View Mirror Poor Appearance

Service Category Vehicle Interior

Section Mirror (int)

Market USA

Lexus Supports
ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2007 – 2009	GS350, GS430, GS450H, LS460	
2008 – 2009	GS460, IS F, LS600H	
2006 – 2009	IS250, IS350	

Introduction

Some 2007 – 2009 GS 350/430/450h/460, 2006 – 2009 model year IS 250/350, 2008 – 2009 model year IS-F, 2007 – 2009 LS 460/460L, and 2008 - 2009 LS 600h models may exhibit a discolored and/or “striped” condition inside the inner rear view mirror glass as shown in Figure 1. An improved service part has been developed to correct this condition.

Figure 1.



Inner Rear View Mirror Poor Appearance

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
752021	R & R INNER REAR VIEW MIRROR (LS 460/460L/600H)	0.3	87810-50310	67	63
			87810-50301		
			87810-50341		
	R & R INNER REAR VIEW MIRROR (GS 350/430/450H/460)	0.2	87810-30341		
	R & R INNER REAR VIEW MIRROR (IS 250/350, IS F)	0.2	87810-53160		
87810-53120					

APPLICABLE WARRANTY

- This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

Production Change Information

This TSIB applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	DRIVETRAIN	PLANT	PRODUCTION CHANGE EFFECTIVE VIN
LS600HL	AWD	Tahara	JTHDU46F#95010759
LS460	2WD		JTHBL46F#95090825
			JTHGL46F#95036681
	AWD		JTHCL46F#95004228
GS350/460	2WD		JTHDL46F#95000927
	AWD		JTHBE96S#90046626
	2WD		JTHCE96S#90024011
GS450H	2WD		JTHBL96S#95003712
			JTHBC96S#95020111
IS250/350	2WD		JTHBK262#95105221
	AWD		JTHCK262#95035292
	2WD		JTHBE262#95023397
	2WD	JTHBK262#82082234	
	AWD	JTHCK262#82027488	
IS-F	2WD	Kyushu	JTHBE262#82016270
			Tahara

Inner Rear View Mirror Poor Appearance

Parts Information

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
87810-50310	Same	Mirror Assy, Inner Rear View	1
87810-50301	Same		1
87810-50341	Same		1
87810-30341	Same		1
87810-53160	Same		1
87810-53120	Same		1

Repair Procedure

- Remove the inner rear view mirror. Refer to the Technical Information System (TIS), applicable model and model year Repair Manual:
 - [2008](#) / [2009](#) LS 600h
Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Removal”
 - [2007](#) / [2008](#) / [2009](#) LS 460/460L
Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Removal”
 - [2006](#) / [2007](#) / [2008](#) / [2009](#) IS 250/350
Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Removal”
 - [2008](#) / [2009](#) IS-F
Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Removal”
 - [2007](#) / [2008](#) / [2009](#) GS 350/430/460
Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Removal”
 - [2007](#) / [2008](#) / [2009](#) GS 450h
Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Removal”
- Install the NEW inner rear view mirror.
Torque: 1.8 N•m (18 kgf•cm, 16in•lbf)
 - [2008](#) / [2009](#) LS 600h
Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Installation”
 - [2007](#) / [2008](#) / [2009](#) LS 460/460L
Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Installation”

Inner Rear View Mirror Poor Appearance

Repair Procedure (Continued)

- [2006](#) / [2007](#) / [2008](#) / [2009](#) IS 250/350
Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Installation”
 - [2008](#) / [2009](#) IS-F
Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Installation”
 - [2007](#) / [2008](#) / [2009](#) GS 350/430/460
Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Installation”
 - [2007](#) / [2008](#) / [2009](#) GS 450h
Vehicle Interior – Mirror (Int) – “Mirror: Inner Rear View Mirror: Installation”
3. For compass calibration, refer to the Technical Information System (TIS), applicable model and model year Repair Manual.
- [2006](#) / [2007](#) / [2008](#) / [2009](#) IS 250/350:
Vehicle Interior – Mirror: Inner Rear View Mirror: Calibration
 - [2007](#) / [2008](#) / [2009](#) GS 350/430/460
Vehicle Interior – Mirror: Inner Rear View Mirror: Calibration
 - [2007](#) / [2008](#) / [2009](#) GS 450h
Vehicle Interior – Mirror: Inner Rear View Mirror: Calibration